

GREG BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representativ	es Present During the Inspection:
Company	Dennis Ware
OGM	Steve Demczak

Inspection Report

Permit Number:	C0070038			
Inspection Type:	PARTIAL			
Inspection Date:	Wednesday, December 14, 2011			
Start Date/Time:	12/14/2011 2:00:00 PM			
End Date/Time:	12/14/2011 4:00:00 PM			
Last Inspection:	Tuesday, November 29, 2011			

Inspector: Steve Demczak,

Weather: <u>Sunny</u>, 30's Snow Covered InspectionID Report Number: <u>2965</u>

Accepted by: jhelfric

1/5/2012

Permitee: PLATEAU MINING CORP
Operator: PLATEAU MINING CORP
Site: WILLOW CREEK MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	14,662.49	
Total Disturbed	71.44	
Phase I	125.41	
Phase II	92.45	
Phase III	92.45	

Mineral Ownership

Types of Operations

✓ Federal
 ✓ Underground
 State
 County
 ✓ Loadout
 ✓ Fee
 ✓ Processing
 ✓ Other
 ✓ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violatios were issued.

Stephen & Demogsk

Inspector's Signature:

Steve Demczak.

Inspector ID Number: 39

Date Wednesday, Dece



oil, gas & minin

Permit Number: C0070038 Inspection Type: PARTIAL

Inspection Date: Wednesday, December 14, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	✓		~	
3.	Topsoil	~		✓	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		~	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	~		✓	
8.	Noncoal Waste	•		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓		✓	
10.	Slides and Other Damage	~		V	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	✓		✓	
13.	Revegetation	✓		~	
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing	V		~	
16.b	Roads: Drainage Controls	✓		Y	
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070038 Inspection Type: PARTIAL

Inspection Date: Wednesday, December 14, 2011

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The DOGM Permit will expire on Dec 23, 2014.

2. Signs and Markers

Identification signs are at the gates to the property.

3. Topsoil

All topsoil was used in reclamation.

4.a Hydrologic Balance: Diversions

Diversions were open and in good condition.

4.c Hydrologic Balance: Other Sediment Control Measures

The reclaimed site is pocked for sediment control.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile is no longer inspected since it has been reclaimed. Permittee received Division approval.

8. Noncoal Waste

The site was clear of non-coal waste materials.

9. Protection of Fish, Wildlife and Related Environmental Issues

No wildlife was noticed during the inspection.

10. Slides and Other Damage

No slides or damage was noticed during the inspection.

12. Backfilling And Grading

The sites are completely reclaimed. All backfilled material was used.

13. Revegetation

This site in my judgment is highly vegetated.

16.a Roads: Construction, Maintenance, Surfacing

A county road goes through the property.

16.b Roads: Drainage Controls

Diversions were open and functioning as designed.